

**SYSTEM REPORT:**  
**[Philips Multi Diagnost Eleva]**

---



AGITO MEDICAL A/S  
Bejlerholm 3B  
9400 Noerresundby  
Denmark  
[www.agitomedical.com](http://www.agitomedical.com)

The images used in the report are for reference only and may show objects that are not included in the offered system configuration. Please refer to the sales order or contact Seller for clarification.

<b>PROJECT NO.</b>	004611
<b>PO INFORMATION</b>	<i>MultiDiagnost Eleva S/N: 170 Cath Lab</i>
<b>PERFORMED BY</b>	Bas Roosdorp
<b>DATE</b>	14 <sup>th</sup> March 2023
<b>SYSTEM INFORMATION</b>	
Manufacturer and model	Philips Multi Diagnost
System model no.	0708MD02
System serial no.	170
System YOM	2011
<b>DETECTOR INFORMATION</b>	
Detector model no.	9896-010-41401
Detector serial no.	113151
Detector YOM	2011
<b>TUBE INFORMATION</b>	
Tube type	N/A (tube replaced 30-09-2021 but the labels were not updated)
Tube model no.	N/A (as above)
Tube serial no.	N/A (as above)
Tube YOM	N/A (as above)
Tube installation date	30-09-2021 as per logbook
Tube housing model no.	989000085182
<b>PATIENT TABLE INFORMATION</b>	
Table model no.	98960020462
Table serial no.	462
Table YOM	2011
Head rest present?	Yes
Positioning pads incl.?	Yes
<b>PDU</b>	
PDU model no.	9896-001-44201
PDU serial no.	167
<b>C ARM CABINET</b>	
Name and model no.	9896-001-41495
Serial no.	167
<b>COOLING CABINET INFORMATION</b>	
Name & model no.	9896-010-33106
Serial no.	124
Usage	100354 hrs on, 100354 hrs run
<b>OTHER CABINETS</b>	
Name and model no.	Xray control - 100 kW
Serial no.	9890-000-70307
<b>WORKSTATION INFORMATION</b>	

Workstation SW options	2k2ImageAcquisition AreaScan AutomatedPixelCalibration CollimationWithoutRadiation CollimatorFilter DoseAwareness DoseReporting Emergency FSInstallation FSRemoteAccess MaxTiltingAngle 90deg MaxXGenPower_80kW RIS MPPS RIS_QueryRetrieve RIS WorklistManagement SubtractedAcquisition VariableTableHeight kVDynarnic
Workstation SW version	R6.3
<b>ACCESSORIES, MANUAL HARD-COPIES AND SOFTWARE DISCS</b>	
Software	Yes present
Manuals	Yes present
CEE certificate	Yes present
<b>MAINTENANCE</b>	
Any major part replacements/service done?	Hospital service log shows 06-02-2023 last PM
Is system logbook present?	Yes
<b>COMMENTS</b>	
Functional condition	Normal working condition
Cosmetic condition	No major damages

<b>PHANTOMS</b>			
Model name	Amount	Model no.	Serial no.
No phantom with the system			

<b>QA TESTING</b> ([List of tests performed + results])		
	Phantom scan (A performance phantom, exposure and fluoro) –	PASS
	Exposure on tools	PASS