

SYSTEM REPORT:



Project No. (Item)	004778
	QA
Inspection done by & Date	G Mountain 06/06/2023
SYSTEM INFORMATION	
Manufacturer and model	Philips MultiDiagnost Eleva
Upgraded System? <ul style="list-style-type: none"> • From which one? • Year of the upgrade? 	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> 6.1.0 to 6.1.2 19/04/2012
System model no.	4598 000 06521
System serial no.	000132
System YOM	Nov 2010
DETECTOR INFORMATION	
Detector model no.	9896-010-41401
Detector serial no.	111251
Detector YOM	March 2011
TUBE INFORMATION	
Tube Type	SRM 0608 ROT-GS 505
Tube Housing model no.	9890-000-85182
Tube Housing serial no.	12682 C 232386
Tube Insert model no.	9890-000-80201
Tube Insert serial no.	232386
Tube YOM	March 2011
Tube installation date	2011
Tube count(s) (mAs, secs, count etc.)	Not Available
PATIENT TABLE INFORMATION	
Table model no.	9896-001-41114
Table serial no.	1103657
Table YOM	2011
TECHNICAL ROOM	
Transformer	
model no.	4512-204-00082
serial no.	11140054
YOM	March 2011
C ARM CABINET	
Name & model no.	Main Cabinet 9896-001-44201
serial no.	135
YOM	2011
FD COOLING CABINET	
Name & model no.	0896-001-43601
serial no.	000063
YOM	2011
OTHER CABINETS?	
Name & model no.	X-ray Control 9890-000-02101
serial no.	10014054
YOM	2011

Name & model no	Main Cabinet 9896-001-44201	
serial no.	135	
YOM	2011	
WORKSTATION INFORMATION (Main)		
Workstation model no.	9896-001-42761	
Workstation serial no.	531100013	
Workstation software version	6.1.2	
Workstation software options	<u>2k2ImageAcquisition</u> <u>3drxAcquisition</u> <u>3drxGeoExtended</u> <u>3drxVerticalAcquisition</u> <u>Areascan</u> <u>CollimationwithoutRadiation</u> <u>CollimatorFilter</u> <u>DoseAwareness</u> <u>DoseReporting</u> <u>Emergency</u> <u>FSInstallation</u> <u>FSRemoteAccess</u> <u>HSA</u> <u>MaxTiltingAngle 90deg</u> <u>MaxGenPower 65kW</u> <u>NonSubtractedDRA</u> <u>RIS MPPS</u> <u>RIS QueryRetrieve</u> <u>RIS WorklistManagement</u> <u>SubtractedAcquisition</u> <u>VariableTableHeight</u> <u>kVDynamic</u>	
ACCESSORIES, MANUAL HARD-COPIES AND SOFTWARE DISCS		
Software	Yes <input checked="" type="checkbox"/>	NO <input type="checkbox"/>
Manuals (list)	Yes <input checked="" type="checkbox"/>	NO <input type="checkbox"/>
Any additional items/accessories?	1. Foot Stand 9896-001-41022 S/N NTS0526	
COMMENTS		
Functional condition	1. Very Good	
Cosmetic condition	1. Very Good	
Q&A TESTING		
	Tests Names Performed	RESULT OF TESTS
		QA
1	Defect Pixels	Pass
2	125kV Fluoro	Pass
3	Field Limitations Frontal	Pass
4	Dose Field Flatness	Pass
5	Stabilisation	Pass
6	Contrast	Pass
7	Sharpness	pass

8	Monitor Performance Test	Pass
---	--------------------------	------