



	QA
Inspection done by & Date	B.Roosdorp 5-OCT-2023
<b>SYSTEM INFORMATION</b>	
Manufacturer and model	GE Innova IGS520
Upgraded System? <ul style="list-style-type: none"> <li>• From which one?</li> <li>• Year of the upgrade?</li> </ul>	Yes <input type="checkbox"/> No <input type="checkbox"/>
System model no.	5127984
System serial no.	EZ25358-3A - 620183BU4
System YOM	2012
<b>DETECTOR INFORMATION</b>	
Detector model no.	20cmFP
<b>TUBE INFORMATION</b>	
Tube Type	Preformix 160
Tube Housing model no.	2216500-2
Tube Housing serial no.	124442CX5
Tube Insert model no.	2216450
Tube Insert serial no.	S/N 232655GI1
Tube YOM	2020 Sept
Tube installation date	2020
<b>PATIENT TABLE INFORMATION</b>	
Table model no.	2261985-2
Table serial no.	706-4990
Table YOM	2012
Head rest present?	Yes v    NO <input type="checkbox"/>
Positioning pads incl.?	Yes v    NO <input type="checkbox"/>
<b>TECHNICAL ROOM</b>	
PDU	
model no.	XR_765_4
serial no.	1000367469

YOM	2012 w33	
C ARM CABINET		
Name & model no.	5127984	
serial no.	5127984	
YOM	2012	
COOLING CABINET INFORMATION (if relevant)		
Name & model no.	SMC Thermo-Con 2375089 rev 3 Part of Coolix 4100	
serial no.	QV- 0593	
UPS		
Name & model no	Digital Energy UPS System	
OTHER CABINETS?		
Name & model no.	C1	
serial no.	2335130-10	
YOM	12C1TQ193	
Name & model no	C2	
serial no.	12C2S0202	
YOM	2012	
WORKSTATION INFORMATION (Main)		
Workstation model no.	Wrong label logged. Check at de-insta	
Workstation serial no.		
GOC Version		
Workstation software version	DL Ghost: DL Ghost Image DL8 - Rev. 25.2.5 DL SW: @(# DL Application Version: DL PATHFINDER 3.2.1 DLAC: AT.4.3-9_7 RTAC AC: ATL.4.3-9_7 RTAC SW: RTAC.PLATFORM6.26.20CM.MONOPLANE Table: RR_POS_TBL_2.3.3.OPFT_17.0 Gantry: RR_POS_GTY_2.3.3PFT_19 JEDI: P636DF1	

Workstation software options	Cardiac & Dynamic InRoom Browser InnovaCentral Touch Screen Fluoro Store Patient Contouring Fluoro UPS Stenosis Analysis Left Ventricle Analysis WorkList MPPS Stent Viz InRoom SA
ACCESSORIES, MANUAL HARD-COPIES AND SOFTWARE DISCS	
Software Manuals (list)	Yes v NO <input type="checkbox"/> Yes v NO <input type="checkbox"/>
<b>MAINTENANCE</b>	
Is system logbook present?	Yes v but out date NO <input type="checkbox"/>
COMMENTS	
Functional condition	1. Normal working condition
Cosmetic condition	1. Patient mattress damaged. Otherwise good condition.

Q&A TESTING			
	Tests Names Performed	RESULT OF TESTS	
		QA	De-Installation
1	Table movements	PASS	
2	C arm movements	PASS	
3	RTAC Subsystem	PASS	
4	Apollo Subsystem	PASS	
5	COLLIMATOR Subsystem	PASS	
6	DL Subsystem	FAIL	
7	Jedi Subsystem	PASS	

8	System Communication	PASS
9	Phantom Exposure	PASS